

State of California
AIR RESOURCES BOARD

EXECUTIVE ORDER D-622

Relating to Exemptions Under Section 27156
of the California Vehicle Code

Enerpulse Inc.
Pulstar Pulse Plug

Pursuant to the authority vested in the Air Resources Board by Section 27156 of the Vehicle Code; and

Pursuant to the authority vested in the undersigned by Section 39515 and Section 39516 of the Health and Safety Code and Executive Order G-02-003;

IT IS ORDERED AND RESOLVED: That the installation of the Pulstar Pulse Plug, manufactured and marketed by the Enerpulse Inc., 2451 Alamo Avenue, Albuquerque, New Mexico 87106, has been found not to reduce the effectiveness of the applicable vehicle pollution control systems and, therefore, is exempt from the prohibitions of Section 27156 of the Vehicle Code for all 2007 and older model year vehicles.

The Pulstar Pulse Plug is a pulse plug designed to replace the stock spark plug. The Pulstar Pulse Plug has no user adjustments.

This Executive Order is valid provided that the installation instructions for the Pulstar Pulse Plug will not recommend tuning the vehicle to specifications different from those submitted by the device manufacturer.

Changes made to the design or operating conditions of the Pulstar Pulse Plug, as exempt by the Air Resources Board, which adversely affect the performance of the vehicle's pollution control system shall invalidate this Executive Order.

This Executive Order shall not apply to any Pulstar Pulse Plug advertised, offered for sale, sold with, or installed on a new motor vehicle prior to or concurrent with transfer to an ultimate purchaser.

Marketing of the Pulstar Pulse Plug using any identification other than that shown in this Executive Order or marketing of the Pulstar Pulse Plug for an application other than those listed in this Executive Order shall be prohibited unless prior approval is obtained from the Air Resources Board.

This Executive Order does not constitute any opinion as to the effect the use of the Pulstar Pulse Plug may have on any warranty either expressed or implied by the vehicle manufacturer.


This Executive Order is granted based on an engineering evaluation and On-Board Diagnostic II (OBD II) system testing on a 2007 model year Honda Accord and 2007 model year Ford 4.0L Mustang. Examination of the OBD II system showed the Pulstar Pulse Plug did not affect OBD II system operation.

THIS EXECUTIVE ORDER DOES NOT CONSTITUTE A CERTIFICATION, ACCREDITATION, APPROVAL, OR ANY OTHER TYPE OF ENDORSEMENT BY THE AIR RESOURCES BOARD OF ANY CLAIMS OF THE APPLICANT CONCERNING ANTI-POLLUTION BENEFITS OR ANY ALLEGED BENEFITS OF THE PULSTAR PULSE PLUG.

No claim of any kind, such as "Approved by the Air Resources Board", may be made with respect to the action taken herein in any advertising or other oral or written communication.

Violation of any of the above conditions shall be grounds for revocation of this order. The order may be revoked only after a ten-day written notice of intention to revoke the order, in which period the holder of the order may request in writing a hearing to contest the proposed revocation. If a hearing is requested, it shall be held within ten days of receipt of the request and the order may not be revoked until a determination is made after the hearing that grounds for revocation exist.

Executed at El Monte, California, this 12 day of July 2007.



Annette Hebert, Chief
Mobile Source Operations Division