

Executive Order G-70-175

Figure 2B-2 Collection Unit Detail

Installer: Place unions at all ports
for ease of installation.

